

Item and Method of Inspection	Reject If
NOTE: These standards only apply to Neighbourhood Zero Emissions vehicles.	
<p>a) Compliance Label A Neighbourhood Zero Emissions Vehicle (NZEV) must display a Compliance Label for a low speed vehicle in accordance with the Motor Vehicle Safety Act (Canada).</p> <p>b) Vehicle Identification Number</p> <p>c) vehicle equipment</p> <p>i) headlamps</p> <p>ii) front and rear turn-signal lamps</p> <p>iii) tail lamps</p> <p>iv) stop lamps</p> <p>v) reflex reflectors</p> <p>vi) slow-moving vehicle warning device All NZEVs manufactured on or after August 6, 2008 must display a slow-moving vehicle warning device in compliance with Section 7B.03 of the Motor Vehicle Act Regulations.</p> <p>vii) exterior mirrors</p>	<p>a) no Compliance Label</p> <ul style="list-style-type: none"> – Compliance Label altered or illegible – Compliance Label does not conform to MVSR requirements <p>b) missing</p> <ul style="list-style-type: none"> – altered – VIN does not conform to the requirements of Section 115, Vehicle Identification Number, of the MVSR <p>i) not two</p> <ul style="list-style-type: none"> – not functioning as OEM – not OEM or equivalent type <p>ii) not two on the front not amber in colour</p> <ul style="list-style-type: none"> – not two on the rear not red or amber in colour – not functioning as OEM – not OEM or equivalent type <p>iii) not two</p> <ul style="list-style-type: none"> – not red illumination – not functioning as OEM – not OEM or equivalent type <p>iv) not two</p> <ul style="list-style-type: none"> – not red illumination – not functioning as OEM – not OEM or equivalent type <p>v) not one red on each side as far to the rear as practicable</p> <ul style="list-style-type: none"> – not one red on rear – not OEM or equivalent type <p>vi) warning device is not present if required</p> <p>vii) not one mounted on driver's side that provides rear view</p> <ul style="list-style-type: none"> – not one interior mounted rear view mirror or one exterior mirror mounted on the passengers side – mirror obstructed or obscured – not OEM or equivalent type

All inspection procedures are visual unless additional inspection procedures are indicated or where applied force is necessary to verify tightness and/or component security.

Item and Method of Inspection	Reject If
viii) parking brake	viii) not equipped – not functioning as OEM
xi) windshield	xi) missing – damaged – windshield does not conform to section 205 of the Motor Vehicle Safety Regulation (MVSR, Glazing Materials)
x) seat belts	x) not one installed at each designated seating position – not anchored as per OEM – not installed as per OEM – not Type 1 or Type 2 seat belt assembly that conforms to section 209, Seat Belt Assemblies, of the MVSR

All inspection procedures are visual unless additional inspection procedures are indicated or where applied force is necessary to verify tightness and/or component security.